

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**No evidence of tracking control BMP's**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**Location shows signs of lack of stabilization BMPs**



**Location shows signs of lack of stabilization BMPs**



**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**N39.55098 W-108.12060**



**Sediment blockage in ditch.**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**N39.55348 W-108.11985**



**Water not draining off road.**



**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**Sediment build up in culvert outlet.**



**Erosion damage from culvert outlet.**



**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location # 435733**



**Erosion damage from culvert outlet.**



**Erosion damage from culvert outlet.**