

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/22/2021

Submitted Date:

01/22/2021

Document Number:

699502175**FIELD INSPECTION FORM**
 Loc ID 320249 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10711Name of Operator: PAINTED PEGASUS PETROLEUM LLCAddress: 16820 BARKER SPRINGS RD #521City: HOUSTON State: TX Zip: 77084**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		jh@p3petro.com	
		dnr_cogccengineering@state.co.us	
		jm@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203226	WELL	SI	06/01/2018	GW	001-08735	PORTER-UPRR 3	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

weeds unmanaged on location

Corrective Action:

Comply with COGCC weed management rules.

Date: 02/01/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

100 BBLS

PBV FIBERGLASS

,

Comment:

Corrective Action:

Date:

Paint

Condition

Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Inspector Name: MEDINA, JUSTIN

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 203226 Type: WELL API Number: 001-08735 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI Needs MIT

Corrective Action: Well must be either:

Date: 01/22/2021

1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or

2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 1/22/21 at approximately 1450 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Porter UPRR 3</p> <p>Company Name- P3</p> <p>API- 05-001-08735</p> <p>In Adams County Colorado.</p> <p>While there, I observed SI well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds unmanaged on location see pics</p> <p>Comply with COGCC weed management rules 2/1/21</p> <p>Well has been shut in since 6/1/18 requires MIT. Contact COGCC engineering</p> <p>Comply with COGCC mechanical integrity test rules. 1/22/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection land owner had plowed field and road was gone heading to wellhead.</p> <p>Took photo from closest point without disturbing plowed/planted field.</p> <p>This is a summary of inspection report.</p>	medinaj	01/22/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402581562	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335907
699502176	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335903