

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2021

Submitted Date:

01/22/2021

Document Number:

701101075

**FIELD INSPECTION FORM**Loc ID 335597 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Armstrong, Jon		jarmstrong@bry.com	
Wilbourn, Don		dwilbourn@bry.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285014	WELL	PR	09/24/2013	GW	045-12349	CHEVRON 5-3D	PR
285015	WELL	PR	07/25/2007	GW	045-12350	CHEVRON 5-1D	PR
285016	WELL	PR	01/12/2010	GW	045-12343	CHEVRON 5-2D	PR
285041	WELL	PR	07/25/2007	GW	045-12352	CHEVRON 5-4D	PR

**General Comment:****COGCC Inspection Report Summary**

I, Inspector Mike Longworth, conducted an inspection at BERRY PETROLEUM COMPANY LLC, CHEVRON L04 696, Location ID: 335597 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

No evidence of tracking control BMP's.

N39.55098 W-108.12060 Sediment blockage in ditch.

N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet. Water not draining off road.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location****Lease Road:**

Type	Main		
comment:	See storm water report.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 2		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	<100 BBLS	PBV STEEL		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:



Inspected Facilities									
Facility ID:	285014	Type:	WELL	API Number:	045-12349	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285015	Type:	WELL	API Number:	045-12350	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285016	Type:	WELL	API Number:	045-12343	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285041	Type:	WELL	API Number:	045-12352	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			N39.55348 W-108.11985
Ditches	Pass					
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
Tracking Pad	Fail	Tracking Pad	Fail	Vehicle Tracking	Fail	No evidence of tracking control BMP's
		Ditches	Fail			N39.55098 W-108.12060 Sediment blockage in ditch.

Comment: No evidence of tracking control BMP's.  
 N39.55098 W-108.12060 Sediment blockage in ditch.  
 N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet. Water not draining off road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C  
 Install, maintain or provide documentation of post construction management plan or BMP's.

Date: 02/06/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402581390	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335805">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335805</a>
701101077	Inspection 701101075 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335801">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335801</a>