

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2021

Submitted Date:

02/09/2021

Document Number:

697003028**FIELD INSPECTION FORM**Loc ID 336648 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 248759 | WELL | PR | 11/01/2020 | GW | 123-16561 | CLEMENT 44-11 | PR |
| 289133 | WELL | PR | 11/01/2020 | GW | 123-24741 | Clement Federal 39-11 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | x 2 | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|---|-------------------------|
| Good Housekeeping: | | |
| Type | DEBRIS | |
| Comment: | Dead vegetation around wellhead area. See attached photo. | |
| Corrective Action: | Comply with Rule 606. | Date: <u>02/26/2021</u> |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | |
|--------------------|-----------|-------|
| Fencing/: | | |
| Type | WELLHEAD | |
| Comment: | Panel x 2 | |
| Corrective Action: | | Date: |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 2 | | |
| Comment: | Bradenhead valves are exposed at surface. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Location #336604 | | | | |
| Corrective Action: | | | | Date: | |

Paint

Inspector Name: Peterson, Tom

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | | |
|--------------------|----|--|-------|--|
| Yes/No | NO | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Flaring:

| | | | | |
|--------------------|--|--|-------|--|
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Inspected FacilitiesFacility ID: 248759 Type: WELL API Number: 123-16561 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/18/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 17 Fluid Type: WATER H2OEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 289133 Type: WELL API Number: 123-24741 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/16/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 25 Fluid Type:End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Seeding | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|-----------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 2/9/2021 at approximately 11:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Clement 44-11 location #336648 in Weld County, Colorado.</p> <p>While there, I observed debris around the wellheads. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 2/26/2021.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | petersont | 02/09/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402595912 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5348553 |
| 697003029 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5348545 |