

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2021

Submitted Date:

02/18/2021

Document Number:

699103198

**FIELD INSPECTION FORM**

Loc ID 447859 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

26 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	<a href="#">All Inspections</a>
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447859	LOCATION	AC			-	Ottenhoff 5N64W29CR	AC
447861	WELL	PR	05/13/2019	OW	123-43639	Ottenhoff 29M-263	PR
447862	WELL	PR	05/11/2019	OW	123-43640	Ottenhoff 29R-423	PR
447863	WELL	PR	05/13/2019	OW	123-43641	Ottenhoff 29R-303	PR
447864	WELL	PR	05/16/2019	OW	123-43642	Ottenhoff 29R-353	PR
447865	WELL	PR	05/16/2019	OW	123-43643	Ottenhoff 29R-253	PR
447866	WELL	PR	05/10/2019	OW	123-43644	Ottenhoff 29U-343	PR
447867	WELL	PR	05/10/2019	OW	123-43645	Ottenhoff 29R-323	PR
447868	WELL	PR	05/06/2019	OW	123-43646	Ottenhoff 29U-243	PR
447869	WELL	PR	05/11/2019	OW	123-43647	Ottenhoff 29R-203	PR
447870	WELL	PR	05/01/2019	OW	123-43648	Ottenhoff 29M-353	PR

**General Comment:**

[Snow covered ground.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	2 USA Compression units not being used, need to be removed for good housekeeping. See attached Photos.		
Corrective Action:	Comply with Rule 606	Date:	05/21/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Sound Walls around compressors		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment:	Panel		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Panel/ Barbwire		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 10		
Comment:	2 Meter Sheds		
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 12		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		

Comment: <a href="#">EcoVaper Zero2 Units</a>		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLS	STEEL AST		
Comment: <a href="#">Loadout control tank. Shares containment with the other crude oil tanks.</a>					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	FIBERGLASS AST		
Comment: <a href="#">Shares containment with crude oil tanks.</a>					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST		40.376500,-104.566900
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	20	OTHER	STEEL AST		40.376400,-104.567300	
Comment:						
Corrective Action:				Date:		

<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	538 BBL					
Other (Type)						

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		

<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	

<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID: <u>447859</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>AC</u>
Producing Well				
Comment: <u>AC</u>				
Corrective Action:		Date:		
Facility ID: <u>447861</u>	Type: <u>WELL</u>	API Number: <u>123-43639</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:		Date:		
BradenHead				
Date of Last Brhd Test: <u>04/05/2020</u>		Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results		Initial Surf Csg Pressure: <u>70</u>	Fluid Type: _____	
		End Surf Csg Pressure: <u>0</u>		
Comment: _____				
Corrective Action:		Date:		
Facility ID: <u>447862</u>	Type: <u>WELL</u>	API Number: <u>123-43640</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:		Date:		
BradenHead				
Date of Last Brhd Test: <u>04/04/2020</u>		Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results		Initial Surf Csg Pressure: <u>65</u>	Fluid Type: _____	
		End Surf Csg Pressure: <u>0</u>		
Comment: _____				
Corrective Action:		Date:		
Facility ID: <u>447863</u>	Type: <u>WELL</u>	API Number: <u>123-43641</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:		Date:		
BradenHead				
Date of Last Brhd Test: <u>11/13/2020</u>		Annual Brhd Completed? <u>Yes</u>		
Last Brhd Test Results		Initial Surf Csg Pressure: <u>50</u>	Fluid Type: <u>NONE</u>	
		End Surf Csg Pressure: <u>0</u>		
Comment: _____				
Corrective Action:		Date:		

Facility ID: 447864 Type: WELL API Number: 123-43642 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/13/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 50 Fluid Type: GAS

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 447865 Type: WELL API Number: 123-43643 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/05/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 68 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 447866 Type: WELL API Number: 123-43644 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 55 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 447867 Type: WELL API Number: 123-43645 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/31/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 447868 Type: WELL API Number: 123-43646 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 58 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 447869 Type: WELL API Number: 123-43647 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/04/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 72 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 447870 Type: WELL API Number: 123-43648 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/05/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 56 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 2/18/21 at approximately 0957hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Ottenhoff 5N64W29CR of PDC Energy, at Location ID # 447859 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      2 USA Compression units not being used, need to be removed for good housekeeping.                      Comply with Rule 606. With a corrective action date of 5/21/21.                      See attached photos.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	02/18/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103199	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354826">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354826</a>