

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/18/2021

Document Number:

700405442**FIELD INSPECTION FORM**Loc ID 316726 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Boulger, Levin		lboulger@31operating.com	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232382	WELL	SI	09/01/2014	OW	103-60014	TRANCO 3A	TA

General Comment:

A follow up inspection of documents:

- 1) Warning letter 401487192 dated 12-15-2017.
- 2) Warning letter 401763225 dated 9-14-2018.
- 3) FIR 679704583 dated 6-21-2019
- 4) FIR 679705631 dated 9-30-2019.
- 5) FIR 679706641 dated 12-17-2019.
- 6) FIR 700404783 dated 12-28-2020.
- 7) FIR 700405321 dated 2-4-2021.

The following compliance issues are uncompleted:

- 1) Acquire MIT or plug well. Complete by 6-30-2018.
- 2) Report past due monthly operations on Form 7. Complete by 1-11-2021.
- 3) Well head gas leak. Photos 2 & 3. Complete by 2-5-2021.

The emergency number 800-209-9762 was called on 2-17-2021 @ 3:20p to report the gas leak again.

Well is located within the town of Rangely limits, on BLM land, a Rule 1202.c sport fish management area, and a Rule 1202.d mule deer severe winter range area.

This is a summary of inspection report 700405442.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production March 2013.		
Corrective Action:	Submit required Form 7(s) to COGCC.		Date: 01/11/2021
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 232382 Type: WELL API Number: 103-60014 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: No audible gas or fluid flow. Well is not connect to a flow line. No pressure gages present. Last recorded production March 2013.Corrective Action: Well must be either:Date: 06/30/20181) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or2) Be properly plugged and abandoned.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 2" of snow on location. No stormwater BMPs were observed.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
12:55	PM	1:00	PM	Wellhead(s)

Comment: FLIR camera used to image the gas leaking at the well. See attached video & photos. Gas odor detected. Snowing at time of inspection.Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.Date: 02/05/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405443	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354827
700405444	FLIR HSM video of gas leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354828
700405445	FLIR video of gas leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354829