

Pit Status Evaluation Form

Pit Overview:

Pit Name: CINQUE 5	Facility ID: 118463
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: MARTIN OIL SERVICE INC / 54200	
Updated Operator:	
Form 15 Pit Permit Doc #: 712492	Permit Date: 10/5/1978
Related Facilities: CINQUE #5 (API 123-07564; Facility ID 239776; Loc ID 317683)	

County: WELD			
Township: 2N	Range: 68W	Section: 31	QQ: SENW
Original Latitude/ Longitude: 40.096607 / -105.048538			
Updated Latitude/ Longitude: 40.096395 / -105.048068			
Basis for Location Change:			
Pit location updated based on aerial imagery (circa 1993)			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|-----------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 712492 | Date: 10/5/1978 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 500161421 | Date: 3/3/1998 |
| Doc #: | Date: |
| Doc #: | Date: |
| <input checked="" type="checkbox"/> Form 27 Remediation Workplan – Project #: 8084 | Date: 10/7/2013 |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> COGIS Document – Doc #: 58832 | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2314633 | Date: 1/24/1996 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 3/23/2020

Timing of Pit Closure:

Closed after 1993 aerial imagery and prior to 1996 pit inventory report

Pit Status Review Summary:

Based on records review and aerial imagery the pit on location was replaced by a tank after 1993 aerial imagery and prior to 1996 pit inventory report. Pit inventories and inspections document a concrete vault on location (shared battery Cinque 1-6). Remediation from concrete vault performed under Remediation Project No 8084 (CL 3/23/2020). Pit Status has been changed to closed.



