



Whiting Oil & Gas Corporation

WILDHORSE 06-0634H CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 427410
Section 6 T9N R59W

2/22/21



Impacted soils no longer at Wellhead