

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2021

Submitted Date:

02/18/2021

Document Number:

695103991

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 309542 _____ Beardslee, Tom _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 10705 _____
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC _____
 Address: 1875 LAWRENCE ST STE 1150 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80202 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 _____ Number of Comments
 1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299602	WELL	PR	07/13/2011	GW	071-09674	Anson 12-19	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Pig Station	# 1	Comment: 4"	Corrective Action:	Date:	
Type: Compressor	# 1	Comment:	Corrective Action:	Date:	
Type: Vertical Separator	# 1	Comment:	Corrective Action:	Date:	
Type: Ancillary equipment	# 1	Comment: TELEMETRY EQUIPMENT	Corrective Action:	Date:	
Type: Bradenhead	# 1	Comment: Phone 3: BRADENHEAD IS NOT PLUMBED TO SURFACE.	Corrective Action: COMPLY WITH RULE 341.	Date: <u>03/08/2021</u>	
Type: Progressive Cavity	# 1	Comment: CBM POWERED	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.	Corrective Action:	Date:	
Type: Deadman # & Marked	# 4	Comment: ALL HAVE MARKERS	Corrective Action:	Date:	
Type: Prime Mover	# 1	Comment: CBM POWERED ENGINE			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 299602 Type: WELL API Number: 071-09674 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Culverts	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
INSPECTION DUE TO COMPLAINT #200449363, I COULD NOT HEAR ANY NOISE COMMING FROM THE DIRECTION OF THE Christine Federal 23-19 (NOT THIS WELL IS DIRECTLY BETWEEN THE Christine Federal 23-19 AND THE COMPLAINANTS RESIDENCE). Phone 4: THIS DRIP IS APPROX. 10' FROM EDGE OF LOCATION TO THE SOUTH BETWEEN THIS WELL AND THE CHRISTINE FEDERAL 23-19. AT TIME OF INSPECTION I SEE NO EVIDANCE THAT THE DRIP HAS BEEN DRAINED ON THE GROUND. THE RESULTS FROM SOUND STUDY SHOW A CALCULATED db OF 42.27	beardslt	02/08/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402602671	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354659
695104001	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354653
695104002	sound study	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354654