

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/18/2021

Document Number:

701101176**FIELD INSPECTION FORM**Loc ID 335597 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10091Name of Operator: BERRY PETROLEUM COMPANY LLCAddress: 11117 RIVER RUN BLVDCity: BAKERSFIELD State: CA Zip: 93311**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                      | Comment |
|-----------------|-------|----------------------------|---------|
| Kellerby, Shaun |       | shaun.kellerby@state.co.us |         |
| Wilbourn, Don   |       | dwilbourn@bry.com          |         |
| Armstrong, Jon  |       | jarmstrong@bry.com         |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 285014      | WELL | PR     | 09/24/2013  | GW         | 045-12349 | CHEVRON 5-3D  | PR          |
| 285015      | WELL | PR     | 07/25/2007  | GW         | 045-12350 | CHEVRON 5-1D  | PR          |
| 285016      | WELL | PR     | 01/12/2010  | GW         | 045-12343 | CHEVRON 5-2D  | PR          |
| 285041      | WELL | PR     | 07/25/2007  | GW         | 045-12352 | CHEVRON 5-4D  | PR          |

**General Comment:****COGCC Follow Inspection Report Summary**

I, Inspector Mike Longworth, conducted a follow up to 01/22/2021 inspection doc # 701101075 at BERRY PETROLEUM COMPANY LLC, CHEVRON L04 696, Location ID: 335597 in Garfield County, Colorado. Location is in close proximity of Parachute creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area)

Action items not addressed from previous inspection:

No evidence of tracking control BMP's.

N39.55098 W-108.12060 Sediment blockage in ditch.

N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet has exposed pipe line. Water not draining off road.

Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Erosion damage from culvert outlet has exposed pipe line needs immediate attention.

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 285014         | Type: | WELL | API Number: | 045-12349 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 285015         | Type: | WELL | API Number: | 045-12350 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 285016         | Type: | WELL | API Number: | 045-12343 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 285041         | Type: | WELL | API Number: | 045-12352 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs    | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|------------------|--------------------------|---------|
| Berms            |                 |                         |                       |                  |                          |         |
| Ditches          |                 |                         |                       |                  |                          |         |
|                  |                 | Ditches                 |                       |                  |                          |         |
| Tracking Pad     | Fail            | Tracking Pad            | Fail                  | Vehicle Tracking | Fail                     |         |
|                  |                 | Culverts                |                       |                  |                          |         |
| Check Dams       |                 |                         |                       |                  |                          |         |
|                  |                 | Check Dams              |                       |                  |                          |         |

Comment: No evidence of tracking control BMP's.  
 N39.55098 W-108.12060 Sediment blockage in ditch.  
 N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet has exposed pipe line. Water not draining off road.  
 Access road shows signs of lack of stabilization BMP's in some areas (rutting is present).  
 Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C  
 Install, maintain or provide documentation of post construction management plan or BMP's.

Date: 02/06/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 402602486    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354498</a> |
| 701101180    | Inspection 701101176 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354496</a> |