

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/17/2021

Submitted Date:

02/17/2021

Document Number:

701101177

FIELD INSPECTION FORMLoc ID 335814 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265355	WELL	PR	03/01/2019	GW	045-08989	CHEVRON 42-5D	PR
281978	WELL	PR	03/01/2019	GW	045-11607	CHEVRON 2F-4D	PR
281979	WELL	PR	03/01/2019	GW	045-11606	CHEVRON 12-4	PR

General Comment:**COGCC Follow Inspection Report Summary**

I, Inspector Mike Longworth, conducted a follow up to 1/22/2021 inspection doc #701101078 at CAERUS PICEANCE LLC, Chevron 42-5D, Location ID: 335814 in Garfield County, Colorado. Location is in close proximity of Parachute creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area).

Action items not addressed from previous inspection:

Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

No evidence of tracking control BMP's.

N39.55098 W-108.12060 Sediment blockage in ditch.

N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet has exposed pipe line.

Water not draining off road.

Corrective action date was 02/06/2021.

Erosion damage at culvert that has exposed gas line needs immediate attention.

Inspector contacted Jason Eckman from Caerus on 2/17/2021 by phone to make Caerus aware of the exposed gas line.

Inspected FacilitiesFacility ID: 265355 Type: WELL API Number: 045-08989 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 281978 Type: WELL API Number: 045-11607 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 281979 Type: WELL API Number: 045-11606 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Vehicle Tracking	Fail	
		Culverts	Fail			
		Check Dams				
		Ditches				
		Tracking Pad	Fail			
Check Dams						
Tracking Pad	Fail					

Comment: Location shows signs of lack of stabilization BMP's in some areas (rutting is present).
 No evidence of tracking control BMP's.
 N39.55098 W-108.12060 Sediment blockage in ditch.
 N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet has exposed pipe line.
 Water not draining off road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C
 Install, maintain or provide documentation of post construction management plan or BMP's.

Date: 02/06/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402602487	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354499
701101178	Inspection 701101177 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5354497