

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2021

Submitted Date:

02/19/2021

Document Number:

700702329**FIELD INSPECTION FORM**
 Loc ID 334892 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262862	WELL	PR	10/03/2002	GW	045-08060	SHIDELER 32-11A2 (G32NEB)	PR
262863	WELL	PR	02/01/2008	GW	045-08061	SHIDELER 32-6A2 (G32NEB)	PR
262864	WELL	PR	02/24/2003	GW	045-08062	SHIDELER 32-3D2 (G32NED)	PR
262865	WELL	PR	05/01/2019	GW	045-08063	SHIDELER 32-1C3 (G32NED)	PR
262893	WELL	PR	10/03/2002	GW	045-08070	SHIDELER 32-10A2 (G32NEB)	PR
262894	WELL	PR	02/22/2003	GW	045-08071	SHIDELER 32-1B2 (G32NED)	PR
262895	WELL	PR	09/30/2002	GW	045-08072	SHIDELER 32-9B2 (G32NEB)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 2/19/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus G32NEB, at Location # 334892 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. This location is within a Density Habitat and Wildlife Management Area. Limited storm water inspection due to snow cover

During this inspection the following possible compliance issues were observed:

1. No evidence of tracking control BMP's
2. Tank battery signage does not meet requirements of new rule 605.e

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	snow covered/ some of access has been plowed		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 7		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 9		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	500 gallon methanol tank in tank battery containment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	2	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	262862	Type:	WELL	API Number:	045-08060	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262863	Type:	WELL	API Number:	045-08061	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262864	Type:	WELL	API Number:	045-08062	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262865	Type:	WELL	API Number:	045-08063	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262893	Type:	WELL	API Number:	045-08070	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262894	Type:	WELL	API Number:	045-08071	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	262895	Type:	WELL	API Number:	045-08072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: This location is within a Density Habitat and Wildlife Management Area. Limited storm water inspection due to snow cover 1. No evidence of tracking control BMP's</p> <p>Corrective Action: Install, maintain or provide documentation of post construction management plan or BMP's Date: 04/19/2021</p> <p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402605021	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5356216
700702332	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5356213