

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2021

Submitted Date:

03/09/2021

Document Number:

692403146

FIELD INSPECTION FORM

Loc ID 335351 Inspector Name: Colby, Lou On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271591	WELL	PR	11/22/2004	GW	045-09903	GMR 28-10D (M27NW)	RI
271592	WELL	PR	11/28/2005	GW	045-09904	GMR 27-12D(M27NW)	RI
271608	WELL	PR	11/25/2004	GW	045-09906	GMR 27-13D(M27NW)	RI
271698	WELL	PR	11/21/2005	GW	045-09935	GMR 28-9D (M27NW)	RI
271761	WELL	PR	11/24/2004	GW	045-09947	GMR 28-16D(M27NW)	RI
272099	WELL	PR	11/19/2004	GW	045-10024	GMR 28-8D (M27NW)	RI
295484	WELL	PR	03/18/2009	GW	045-15773	GMR 27-13A (M27NW)	RI
295485	WELL	PR	04/29/2009	GW	045-15774	GMR 27-14A(M27NW)	RI
295488	WELL	PR	04/19/2009	GW	045-15775	GMR 27-11D (M27NW)	RI
295489	WELL	PR	04/29/2009	GW	045-15776	GMR 27-12A(M27NW)	RI
296343	WELL	PR	04/16/2009	GW	045-15993	GMR 27-13B (M27NW)	RI
296344	WELL	PR	04/16/2009	GW	045-15994	GMR 27-12B (M27NW)	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Possible leaking from tank; yellowish scum on ice surface. Refer to Photo log attached.					
Corrective Action: Investigate Leak within 24 hours; remedy condition as relevant to findings, adhering to appropriate timelines.					Date: 03/11/2021

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 271591 Type: WELL API Number: 045-09903 Status: PR Insp. Status: RIFacility ID: 271592 Type: WELL API Number: 045-09904 Status: PR Insp. Status: RIFacility ID: 271608 Type: WELL API Number: 045-09906 Status: PR Insp. Status: RIFacility ID: 271698 Type: WELL API Number: 045-09935 Status: PR Insp. Status: RIFacility ID: 271761 Type: WELL API Number: 045-09947 Status: PR Insp. Status: RIFacility ID: 272099 Type: WELL API Number: 045-10024 Status: PR Insp. Status: RIFacility ID: 295484 Type: WELL API Number: 045-15773 Status: PR Insp. Status: RIFacility ID: 295485 Type: WELL API Number: 045-15774 Status: PR Insp. Status: RIFacility ID: 295488 Type: WELL API Number: 045-15775 Status: PR Insp. Status: RIFacility ID: 295489 Type: WELL API Number: 045-15776 Status: PR Insp. Status: RIFacility ID: 296343 Type: WELL API Number: 045-15993 Status: PR Insp. Status: RIFacility ID: 296344 Type: WELL API Number: 045-15994 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Snow cover prevented assessment of Interim Reclamation areas; though re-contouring appears nicely executed and that site is well maintained.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Limited storm water inspection due to snow cover. Pad area overall, appears stable though soft area near exit (initiating rutting), will require seasonal maintenance.						
Corrective Action: <input type="text"/>						Date: <input type="text"/>
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692403164	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5371399