

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2021

Submitted Date:

03/17/2021

Document Number:

701101287

**FIELD INSPECTION FORM**Loc ID 324269 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271251	WELL	SI	09/01/2020	GW	045-09852	GASAWAY 6224X	SI

**General Comment:**

Follow up to 11/12/2020 inspection # 701100746

Nearest county road added to well signage.

Fencing around well has been repaired.

Doors have been rehung on separator.

During this inspection the following possible compliance issues were observed:

Stack of lumber at well.

Container label is faded.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location is in close proximity of Brush Creek and Roan Creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area)

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Container label is faded.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	06/18/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Nearest county road added to well signage.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Stack of lumber at well.		
Corrective Action:	Comply with Rule 606	Date:	03/26/2021

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Fencing around well has been repaired.		
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Doors have been rehung on separator.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container at meter shed.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 271251	Type: WELL	API Number: 045-09852	Status: SI	Insp. Status: SI
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Culverts				
Berms						
Gravel						
		Gravel				
Compaction						
Ditches						
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402632051	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378837</a>
701101288	Inspection 701101287 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378831">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5378831</a>