

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/10/2021

Submitted Date:

04/10/2021

Document Number:

700702557

**FIELD INSPECTION FORM**

Loc ID 335434	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 22 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272857	WELL	PR	03/10/2005	GW	045-10180	FEDERAL RWF 13-19	PR
272858	WELL	PR	05/13/2005	GW	045-10179	FEDERAL RWF 313-19	PR
272859	WELL	PR	05/25/2005	GW	045-10178	FEDERAL RWF 413-19	PR
272860	WELL	PR	03/27/2005	OW	045-10177	FEDERAL RWF 513-19	PR
301013	WELL	PR	05/31/2010	GW	045-18073	FEDERAL RWF 314-19	PR
452657	WELL	PR	12/17/2018	OW	045-23759	FEDERAL PA 532-24	PR
452658	WELL	PR	12/17/2018	OG	045-23760	FEDERAL PA 433-24	PR
452661	WELL	PR	01/02/2019	OG	045-23763	FEDERAL PA 332-24	PR
452663	WELL	PR	12/17/2018	OG	045-23764	FEDERAL PA 434-24	PR
452673	WELL	PR	01/02/2019	OG	045-23774	FEDERAL PA 432-24	PR
452675	WELL	PR	01/02/2019	OG	045-23776	FEDERAL PA 34-24	PR
452682	WELL	PR	12/17/2018	OG	045-23782	FEDERAL PA 334-24	PR
452686	WELL	PR	12/17/2018	OG	045-23786	FEDERAL PA 32-24	PR
452689	WELL	PR	12/17/2018	OG	045-23788	FEDERAL PA 333-24	PR
452692	WELL	PR	12/17/2018	OG	045-23791	FEDERAL PA 533-24	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 4/8/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 13-19, at Location # 335434 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.

During this inspection the following possible compliance issues were observed:

1. Location show signs of lack of stabilization/compaction
2. Staining throughout location
3. Neither the well heads or the battery signage provides API #'s
4. Berm around contaminated soil on corner of location is in need of maintenance.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	signage missing API #'s		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	signage missing API #'s		
Corrective Action:	Comply with rule 605	Date:	05/10/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Staining throughout location		
Corrective Action:	remove all stained material	Date:	05/10/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 15		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 15		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at well heads in a plastic containment		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	272857	Type:	WELL	API Number:	045-10180	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272858	Type:	WELL	API Number:	045-10179	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272859	Type:	WELL	API Number:	045-10178	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	272860	Type:	WELL	API Number:	045-10177	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	301013	Type:	WELL	API Number:	045-18073	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452657	Type:	WELL	API Number:	045-23759	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452658	Type:	WELL	API Number:	045-23760	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452661	Type:	WELL	API Number:	045-23763	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	452663	Type:	WELL	API Number:	045-23764	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452673	Type:	WELL	API Number:	045-23774	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452675	Type:	WELL	API Number:	045-23776	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452682	Type:	WELL	API Number:	045-23782	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452686	Type:	WELL	API Number:	045-23786	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452689	Type:	WELL	API Number:	045-23788	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	452692	Type:	WELL	API Number:	045-23791	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	producing								
Corrective Action:						Date:			

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Berms				
Berms						
		Culverts				
Compaction	Fail					

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.  
 1. Location show signs of lack of stabilization/compaction  
 2. Berm around contaminated soil on corner of location is in need of maintenance.

Corrective Action: **Install or repair required BMPs**

Date: 05/10/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402654549	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399956">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399956</a>
700702563	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399951</a>