

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2021

Submitted Date:

04/12/2021

Document Number:

701500280

FIELD INSPECTION FORM

Loc ID 398837 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Dooling, Jes	832-624-0810	jessica.dooling@exxonmobil.com	Lead regulatory coordinator
Thompson, Bud		BLThomps@BLM.gov	
Sutton, Derek		derek_sutton@xtoenergy.com	Area foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301780	WELL	PR	08/01/2020	GW	103-11474	Piceance Creek Unit 296-6A10	PR
301781	WELL	PR	09/26/2011	GW	103-11475	PICEANCE CREEK UNIT 296-6A1	PR
301783	WELL	PR	11/01/2020	GW	103-11477	PICEANCE CREEK UNIT 296-6A6	PR
301784	WELL	PR	11/15/2011	GW	103-11478	PICEANCE CREEK UNIT 296-6A5	PR
301785	WELL	PR	08/01/2018	GW	103-11479	PICEANCE CREEK UNIT 296-6A8	PR
301786	WELL	PR	05/29/2012	GW	103-11480	Piceance Creek Unit 296-6A4	PR
301787	WELL	PR	06/01/2020	GW	103-11481	PICEANCE CREEK UNIT 296-6A3	PR
301788	WELL	PR	11/15/2011	GW	103-11482	PICEANCE CREEK UNIT 296-6A7	PR
301789	WELL	PR	11/01/2020	GW	103-11483	PICEANCE CREEK UNIT 296-6A9	PR

General Comment:

A routine inspection identified the following compliance issues:

- 1) Compaction incomplete on location. Photo 7. Complete by 6-12-2021.
- 2) Missing sign at well 296-6A10. Photo 3. Complete by 6-12-2021.

Location is within a CDPHE Reg 42 Limited use & quality area, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, Rule 309.e.1 Greater sage grouse general habitat management area, and a Black bear area.

This is a summary of inspection report 701500280.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Sign at location entrance.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Missing sign at well 296-6A10.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 06/12/2021

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 9		
Comment:	Bradenhead access present.		
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		
Comment:	Well manifold, communication building, pump on trailer.		
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical containers.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	301780	Type:	WELL	API Number:	103-11474	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301781	Type:	WELL	API Number:	103-11475	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301783	Type:	WELL	API Number:	103-11477	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301784	Type:	WELL	API Number:	103-11478	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301785	Type:	WELL	API Number:	103-11479	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301786	Type:	WELL	API Number:	103-11480	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301787	Type:	WELL	API Number:	103-11481	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	301788	Type:	WELL	API Number:	103-11482	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Facility ID: 301789 Type: WELL API Number: 103-11483 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Ditches				Material Handling And Spill Prevention		
Compaction	Fail					
Berms						

Comment: Cattle guard across location entrance. Tracking on location near wells.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/12/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402655167	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400396
701500281	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400388