

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/12/2021

Document Number:

701500284

FIELD INSPECTION FORM

Loc ID 413466 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 21 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator
Thompson, Bud		BLThomps@BLM.gov	
Sutton, Derek		derek_sutton@xtoenergy.com	Area foreman
Dooling, Jes	832-624-0810	jessica.dooling@exxonmobil.com	Lead regulatory coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412626	WELL	PR	02/16/2012	GW	103-11529	Piceance Creek Unit 296-6B5	PR
412628	WELL	PR	02/18/2012	GW	103-11530	Piceance Creek Unit 296-6B4	PR
412650	WELL	PR	09/01/2020	GW	103-11531	Piceance Creek Unit 296-6B7	PR
412651	WELL	PR	01/01/2021	GW	103-11534	Piceance Creek Unit 296-6B8	PR
412652	WELL	PR	02/26/2012	GW	103-11533	Piceance Creek Unit 296-6B10	PR
412653	WELL	PR	02/27/2012	GW	103-11532	Piceance Creek Unit 296-6B9	PR
413071	WELL	PR	02/24/2012	GW	103-11546	Piceance Creek Unit 296-6B1	PR
413072	WELL	SI	02/01/2020	GW	103-11545	PICEANCE CREEK UNIT 296-6B2	SI
413073	WELL	PR	12/01/2017	GW	103-11547	Piceance Creek Unit 296-6B6	PR
413074	WELL	PR	02/21/2012	GW	103-11548	Piceance Creek Unit 296-6B3	PR

General Comment:

A routine inspection identified the following compliance issues:

- 1) Compaction incomplete on location. Photo 6. Complete by 6-12-2021.
- 2) Missing sign at well 296-6A10. Photo 2. Complete by 6-12-2021.

Location is within a CDPHE Reg 42 Limited use & quality area, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, Rule 309.e.1 Greater sage grouse general habitat management area, and a Black bear area.

This is a summary of inspection report 701500284.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Missing sign at well 296-6A10.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/12/2021
Type	BATTERY		
Comment:	Sign at location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Well manifold & communication building.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical containers.		
Corrective Action:		Date:	
Type: Bradenhead	# 10		

Comment:	Bradenhead access present.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	412626	Type:	WELL	API Number:	103-11529	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	412628	Type:	WELL	API Number:	103-11530	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	412650	Type:	WELL	API Number:	103-11531	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	412651	Type:	WELL	API Number:	103-11534	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	412652	Type:	WELL	API Number:	103-11533	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	412653	Type:	WELL	API Number:	103-11532	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	413071	Type:	WELL	API Number:	103-11546	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	413072	Type:	WELL	API Number:	103-11545	Status:	SI	Insp. Status:	SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 413073 Type: WELL API Number: 103-11547 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

Facility ID: 413074 Type: WELL API Number: 103-11548 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap				Material Handling And Spill Prevention		
Ditches						
Retention Ponds						
Gravel		Gravel				

Comment: [Cattle guard across location entrance. Tracking on location near processing equipment.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/12/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402655170	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400398
701500285	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400390