


# CAERUS PICEANCE LLC

## PUCKETT-66S96W 31SENW

### Location # 335297



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**No NFPA sticker on tank.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**NFPA sticker is damaged.**

**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Buried electric cables exposed.**



**Buried electric cables exposed.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Electric wire cable pieces on edge of location.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Well signs are illegible and missing api#s.**



**Well signs are illegible and missing api#s.**

**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Well signs are illegible and missing api#s.**



**Well signs are illegible and missing api#s.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Well signs are illegible and missing api#s.**



**DOT diamond is faded.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Sediment in culvert.**



**Sediment in culvert.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**





**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Erosion created from flow of culvert.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Culvert basin needs cleaned out.**



**CAERUS PICEANCE LLC**  
**PUCKETT-66S96W 31SENW**  
**Location # 335297**



**Damaged culvert.**



**Sediment and rock in culvert.**