

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2021

Submitted Date:

04/19/2021

Document Number:

679603810

FIELD INSPECTION FORM
 Loc ID 451277 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

26 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451510	WELL	PR	09/05/2018	OW	123-45101	Falken 33N-9B-L	PR
451514	WELL	PR	09/24/2018	OW	123-45103	Falken 32N-9B-L	PR
451515	WELL	PR	09/05/2018	OW	123-45104	Falken 4N-14A-S	PR
451518	WELL	PR	09/22/2018	OW	123-45106	Falken State 34N-9C-L	PR
451519	WELL	PR	09/05/2018	OW	123-45107	Falken 33N-9A-L	PR
451530	WELL	PR	09/08/2018	OW	123-45111	Falken 30N-14B-S	PR
451532	WELL	PR	09/05/2018	OW	123-45112	Falken 33C-9-L	PR
451535	WELL	PR	09/05/2018	OW	123-45114	Falken 33N-9C-L	PR
451536	WELL	PR	09/27/2018	OW	123-45115	Falken 32C-9-L	PR
451537	WELL	PR	09/26/2018	OW	123-45116	Falken 31C-14-S	PR
451539	WELL	PR	09/22/2018	OW	123-45117	Falken 9C-9-L	PR
451542	WELL	PR	09/07/2018	OW	123-45119	Falken 30C-14-S	PR
451544	WELL	PR	09/22/2018	OW	123-45120	Falken 16N-9B-L	PR
451546	WELL	PR	09/05/2018	OW	123-45121	Falken 31N-14B-S	PR
451547	WELL	PR	09/25/2018	OW	123-45122	Falken 9N-9C-L	PR
451551	WELL	PR	09/05/2018	OW	123-45124	Falken 4N-14C-S	PR
451552	WELL	PR	09/24/2018	OW	123-45125	Falken State 34C-9-L	PR
451555	WELL	PR	09/23/2018	OW	123-45127	Falken 16C-9-L	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at one wellhead. See attached photo.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes Per Rule 1002.(2).d.	Date:	05/19/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 18		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 18		
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 18		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 5		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:	23 TOTAL		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	451510	Type:	WELL	API Number:	123-45101	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451514	Type:	WELL	API Number:	123-45103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451515	Type:	WELL	API Number:	123-45104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451518	Type:	WELL	API Number:	123-45106	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451519	Type:	WELL	API Number:	123-45107	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451530	Type:	WELL	API Number:	123-45111	Status:	PR	Insp. Status:	PR
Facility ID:	451532	Type:	WELL	API Number:	123-45112	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451535	Type:	WELL	API Number:	123-45114	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451536	Type:	WELL	API Number:	123-45115	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451537 Type: WELL API Number: 123-45116 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451539 Type: WELL API Number: 123-45117 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451542 Type: WELL API Number: 123-45119 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451544 Type: WELL API Number: 123-45120 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451546 Type: WELL API Number: 123-45121 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451547 Type: WELL API Number: 123-45122 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451551 Type: WELL API Number: 123-45124 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 451552 Type: WELL API Number: 123-45125 Status: PR Insp. Status: PR				

<u>Producing Well</u>			
Comment:	PR		
Corrective Action:		Date:	
Facility ID:	451555	Type:	WELL
API Number:	123-45127	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	PR		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS AS FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603584. All previous corrective actions that were assigned to this location have been resolved. One new corrective action was observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Monday, April 19, 2021 at approximately 11:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at FLAKEN 9-11 PAD (PDC Energy), at location #: 451277 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be stained soil at one wellhead. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: May 19, 2021) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	04/19/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402665276	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408564
679603811	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408551