

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2021

Submitted Date:

04/20/2021

Document Number:

700702602

**FIELD INSPECTION FORM**

Loc ID 335196 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
6 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC		shaun.kellerby@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, COGCC		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281756	WELL	PR	02/08/2007	GW	045-11530	MEAD 30-12C	PR
281759	WELL	PR	02/08/2007	GW	045-11532	MEAD 30-13D	PR
281763	WELL	PR	02/08/2007	GW	045-11534	MEAD 30-13C	PR
281765	WELL	PR	02/08/2007	GW	045-11536	MEAD 30-14A	PR

**General Comment:**

COGCC Inspection Report Summary  
 On Monday 4/19/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Mead 30-13, at Location # 335196 in Garfield county Colorado.  
 While there, I observed normal production operations. Inventory on location is the same as previous inspection. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad. C/A from previous inspection document #700702442 for location lack of stabilization/compaction is still within C/A date (5/19/2021).  
 This inspection was focused on the tracking C/A from previous inspection # 700702442. C/A has not been completed, therefore C/A date remains the same.  
 During this inspection the following possible compliance issues were observed:  
 1. Access still show signs of lack of stabilization/compaction. Tracking is evident onto county road 317 (beaver creek road) Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	lease road show signs of lack of stabilization/compaction. Tracking is evident onto County road 317 (Beaver Creek Road)		
Corrective Action:	Maintain vehicle tracking BMPs, control potential sediment discharges from operational roads, well pads, and other unpaved surfaces to comply with rule 1002.f.(2)F.	Date:	03/25/2021

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:	<input style="width: 90%;" type="text"/>		
Corrective Action:	<input style="width: 80%;" type="text"/>		Date: <input style="width: 20%;" type="text"/>

**Flaring:**

Type			
Comment:	<input style="width: 90%;" type="text"/>		
Corrective Action:	<input style="width: 80%;" type="text"/>		Date: <input style="width: 20%;" type="text"/>

Inspected Facilities									
Facility ID:	281756	Type:	WELL	API Number:	045-11530	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	281759	Type:	WELL	API Number:	045-11532	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	281763	Type:	WELL	API Number:	045-11534	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	281765	Type:	WELL	API Number:	045-11536	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402664271	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408048</a>
700702605	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408044">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408044</a>