

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/19/2021

Submitted Date:

04/20/2021

Document Number:

701101386

FIELD INSPECTION FORMLoc ID 335297 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259587	WELL	PR	03/21/2001	GW	045-07757	PUCKETT 12-31D	PR
259588	WELL	PR	03/21/2001	GW	045-07758	PUCKETT 22-31D	PR
259589	WELL	PR	01/31/2002	GW	045-07759	PUCKETT 21-31D	PR
259590	WELL	SI	08/01/2020	GW	045-07760	PUCKETT 13-31D	SI

General Comment:**COGCC Routine Inspection Report Summary**

During this inspection the following possible compliance issues were observed:

- Well signs are illegible and missing api#s.
- 200 bbl NFPA label is damaged. 300 bbl tank has no NFPA and contents.
- DOT diamond is faded on chemical container.
- Cable ends still exposed. Previous corrective action item from 8/11/2017 inspection doc # 689700135 and 07/10/2018 doc # 689701600
- Culverts on access road need cleaned out and maintained. Aprx. 6 ft metal culvert creating erosion on outlet side.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	DOT diamond is faded.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/20/2021
Type	TANK LABELS/PLACARDS		
Comment:	200 bbl NFPA label is damaged. 300 bbl tank has no NFPA and contents.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/20/2021
Type	WELLHEAD		
Comment:	Well signs are illegible and missing api#s.		
Corrective Action:	Install sign to comply with Rule 605.d. Install sign to comply with Rule 605.g.	Date:	07/20/2021
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Cable ends still exposed. Previous corrective action item from 8/11/2017 inspection doc # 689700135 and 07/10/2018 doc # 689701600		
Corrective Action:	Comply with Rule 606.	Date:	05/07/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment:		
Corrective Action:		Date:
Type	WELLHEAD	
Comment:		
Corrective Action:		Date:

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 259587 Type: WELL API Number: 045-07757 Status: PR Insp. Status: PR**Producing Well**Comment: Producing wellCorrective Action: Date: Facility ID: 259588 Type: WELL API Number: 045-07758 Status: PR Insp. Status: PR**Producing Well**Comment: Producing wellCorrective Action: Date: Facility ID: 259589 Type: WELL API Number: 045-07759 Status: PR Insp. Status: PR**Producing Well**Comment: Producing wellCorrective Action: Date: Facility ID: 259590 Type: WELL API Number: 045-07760 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: Last production record July 2020Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
Check Dams						
				Material Handling And Spill Prevention	Pass	Chemical container on location
Seeding						sloughing shale and sediment burying seeded area.
		Compaction				
		Culverts	Fail			
Ditches						sloughing shale and sediment
Berms						
		Berms				

Comment: [Culverts on access road need cleaned out and maintained. Aprx. 6 ft metal culvert creating erosion on outlet side.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 05/07/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402664274	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408051
701101387	Inspection 701101386 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408047