

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 1 no BMP's in place between active water way (riparian habitat) and open excavation.**



**Photo 2 No tracking pad BMP on entrance # 1**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 3 No inlet protection around storm drain.**



**Photo 4 no BMP's in place between active water way (riparian habitat) and open excavation.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**




**Photo 5 No tracking pad BMP**



**Photo 6 Debris: dead weeds and not BMP between produced water tank excavation and water way.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 7 Outlet of inlet drain not protected. No BMP between produced water tank and water way.**



**Photo 8 Improper safety fence around work area.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 9 No BMP's around work site to protect run on or run off.**



**Photo 10 unused equipment.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 11 Unused equipment**



**Photo 12 improper safety fence around work zone and open excavation.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 13 Improper safety fence around work site.**



**Photo 14 exposed lines not plugged or capped.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 15 loc pic**



**Photo 16 loc pic**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



Colorado Oil and Gas Conservation Commission  
40.11678, -104.96806, 1487.4m  
Apr 19, 2021 10:54:10

**Photo 17 loc pic**



Colorado Oil and Gas Conservation Commission  
40.11678, -104.96806, 1487.7m  
Apr 19, 2021 10:54:14

**Photo 18 unused equipment and improper safety fencing  
around work site.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 19 improper fencing around open excavation and work site.**



**Photo 20 loc pic**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 21 unsafe and improper fencing around open excavation.  
What appears to be visible ground water.**



**Photo 22 What appears to be visible ground water, unsupported  
flow lines. Fencing and equipment on edge of vertical bank.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 23 Piping cut and in water**



**Photo 24 open excavation pic. No BMP's in place to prevent storm water from entering excavation.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 25 open excavation pic**



**Photo 26 loc pic**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 27 open ended pipe in open excavation.**



**Photo 29 loc pic**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



Colorado Oil and Gas Conservation Commission  
40.11656, -104.96743, 1481.6m  
Apr 19, 2021 10:57:00

**Photo 30 Meter house. Sales line is in the open position.**



Colorado Oil and Gas Conservation Commission  
40.1167, -104.96729, 1484.0m  
Apr 19, 2021 10:57:27

**Photo 31 Separator and Meter house. Meter does not have annual calibration performed.**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



Colorado Oil and Gas Conservation Commission  
40.1167, -104.9673, 1484.3m  
Apr 19, 2021 10:57:31

**Photo 32 Water tank and compressor building.**



Colorado Oil and Gas Conservation Commission  
40.11677, -104.96741, 1484.5m  
Apr 19, 2021 10:57:56

**Photo 33 Compressor breaker box not LOTO accessible to the public.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 34 not tracking pad BMP**



**Photo 35 Unused equipment**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 36 Improper fencing around open excavation and work site**




**Photo 37 Stained soil and mechanical issues inside compressor building.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 38 Stained soil and mechanical issues inside compressor building**



**Photo 39 Stained soil and mechanical issues inside compressor building**

**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



Colorado Oil and Gas Conservation Commission  
40.11662, -104.96735, 1484.4m  
Apr 19, 2021 11:01:17

**Photo 40 Valves to sales meter in the open position**



Colorado Oil and Gas Conservation Commission  
40.11684, -104.96693, 1484.9m  
Apr 19, 2021 11:03:41

**Photo 41 side walk from school is approx. 100 feet form remediation work site.**



**Inspection Photos**  
**Location Name: Grant Tank BTRY**  
**Location ID: 446484**



**Photo 43 Cross walk guard escorts elementary kids across county road.**



**Photo 44 electric box not LOTO.**

Inspection Photos  
Location Name: Grant Tank BTRY  
Location ID: 446484



Photo 45 Separator not properly LOTO



Photo 46 Separator not properly LOTO.