

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

699303772

FIELD INSPECTION FORM

Loc ID 317922 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240187	WELL	PR	02/01/2020	OW	123-07975	BANGERT 42-19	PR
453314	TANK BATTERY	AC	12/06/2017		-	Bangert 41-19 & 42-19 battery	AC

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil by WH and in PJ base		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	07/27/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well site has barb wire fencing around well site is in disrepair.		
Corrective Action:	Comply with rule 1002..(2).D Self-inspection, maintenance, and good housekeeping procedures.	Date:	07/27/2021

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation, electric panel, meter box and transformers		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	no card in meter box to indicate calibration status.		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 429 & 430. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).		Date: 07/27/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	shares containment with crude tank	
Corrective Action:		Date:

Wells Served By Facilities Above

AirsID

API Number
123-07975
123-09150

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240187 Type: WELL API Number: 123-07975 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/03/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 453314 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 4/27/2021 at approximately 1345 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: center;">Bangert 42-19 at API #05-123- 07975 in Weld County Colorado. While there, I observed a wellsite and tank battery, PR at time of inspection. During this inspection the following possible compliance issues were observed: Rule 429/430 Measurement of Oil & Gas: No card in meter box to indicate calibration status, CA date 7-27-2021. Rule 1002..(2).D house keeping: Stained soil by the WH and fencing in disrepair around well site, CA date 7-27-2021. See attached photos. Location: wet/muddy, Weather: cloudy/overcast raining. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	04/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402672791	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414475
699303773	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414472