



**Inspected Facilities**

Facility ID: 479913 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: spill reported by initial form 19 in tiemely manner

Corrective Action: supplemental form 19 to address COAs in approved initial form 19 due in 10 days follwoing discovery Date: 05/13/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681713	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422378">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422378</a>
697601336	general area of spill	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422368">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422368</a>
697601338	initial excavation at spill	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422369">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422369</a>