

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2021

Submitted Date:

05/06/2021

Document Number:

699803039

**FIELD INSPECTION FORM**

Loc ID 312363 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

**Findings:**

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email                                 | Comment |
|-----------------|-------|---------------------------------------|---------|
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            |         |
| , Laramie       |       | cogccnotifications@laramie-energy.com |         |

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Thursday 5/6/21 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC BCU /12D Pad, Location #312363 in Mesa County Colorado.  
While there, I observed normal production operations.  
During this inspection the following compliance issues were observed:

1) No battery sign located at the tank battery with a corrective action date of 8/6/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

**Location**

Overall Good:

| <b>Signs/Marker:</b> |  |       |            |
|----------------------|--|-------|------------|
| Type                 | BATTERY  |       |            |
| Comment:             | No battery sign located at the tank battery.                       |       |            |
| Corrective Action:   | A permanent, conspicuous sign will be located at the tank battery. | Date: | 08/06/2021 |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | WELLHEAD   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | CONTAINERS   |       |            |
| Comment:             | Chemical tank  |       |            |
| Corrective Action:   |  | Date: |            |

|                           |                    |       |       |
|---------------------------|--------------------|-------|-------|
| Emergency Contact Number: |                    |       |       |
| Comment:                  | 911/1-800-891-6191 |       |       |
| Corrective Action:        |                    | Date: | _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

| <b>Fencing/:</b>   |                                   |       |  |
|--------------------|-----------------------------------|-------|--|
| Type               | LOCATION                          |       |  |
| Comment:           | Barbed wire fence around location |       |  |
| Corrective Action: |                                   | Date: |  |

| <b>Equipment:</b>         |  |       | corrective date |
|---------------------------|--|-------|-----------------|
| Type: Bradenhead          | # 1  |       |                 |
| Comment:                  | Pressure transducer located on braden head. All braden head valves are accessible. |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Plunger Lift        | # 1  |       |                 |
| Comment:                  | Injection well   |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Plunger Lift        | # 1  |       |                 |
| Comment:                  |  |       |                 |
| Corrective Action:        |  | Date: |                 |
| Type: Ancillary equipment | # 1  |       |                 |

|                                   |                    |       |  |
|-----------------------------------|--------------------|-------|--|
| Comment:                          | Chemical tank      | Date: |  |
| Corrective Action:                |                    | Date: |  |
| Type: Other                       | # 1                |       |  |
| Comment:                          | Generator          | Date: |  |
| Corrective Action:                |                    | Date: |  |
| Type: Bird Protectors             | # 1                |       |  |
| Comment:                          |                    | Date: |  |
| Corrective Action:                |                    | Date: |  |
| Type: Other                       | # 1                |       |  |
| Comment:                          | Trash bin          | Date: |  |
| Corrective Action:                |                    | Date: |  |
| Type: Other                       | # 1                |       |  |
| Comment:                          | Pump in pump house | Date: |  |
| Corrective Action:                |                    | Date: |  |
| Type: Horizontal Heated Separator | # 1                |       |  |
| Comment:                          |                    | Date: |  |
| Corrective Action:                |                    | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 2 | 400 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity                | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------|---------------------|---------------------|-------------|
| Metal              | Adequate                | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Centralized containment |                     |                     |             |
| Corrective Action: |                         |                     |                     |             |
|                    |                         |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER     | 6 | 300 BBLs | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |

Other (Type) \_\_\_\_\_

**Berms**

| Type   | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Metal  | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment: <a href="#">Centralized containment</a> |          |                     |                     |             |
| Corrective Action:                               |          |                     |                     | Date:       |

**Venting:**

| Yes/No             | NO |       |  |
|--------------------|----|-------|--|
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment       |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------------|
|                  |                 | Rip Rap                 |                       |  |                          |               |
|                  |                 | Gravel                  |                       |  |                          |               |
| Gravel           |                 |                         |                       |  |                          |               |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          | Chemical tank |
| Waddles          |                 |                         |                       |  |                          |               |
|                  |                 | Check Dams              |                       |  |                          |               |
| Ditches          |                 |                         |                       |  |                          |               |
|                  |                 | Culverts                |                       |  |                          |               |
|                  |                 | Ditches                 |                       |  |                          |               |
|                  |                 | Berms                   |                       |  |                          |               |
| Compaction       |                 |                         |                       |  |                          |               |
| Sediment Traps   |                 |                         |                       |  |                          |               |
| Berms            |                 |                         |                       |  |                          |               |
|                  |                 | Sediment Traps          |                       |  |                          |               |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <a href="#">Refer to Signs/Marker for corrective actions.</a> | depaoloc | 05/06/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 402682828    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423482</a> |
| 699803040    | Photos for Insp. #699803039 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423470</a> |