

# Inspection Photos

API: 071-06340

Operator: OGRIS OPERATING LLC

Inspection Date: 5/17/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 5/17/2021

## Inspection Photos



**Photo 1.** There is water from the river pooling onto the road in this area. BMP's need to be installed to prevent erosion of this area. E.G. Berm. Diversion ditch, culvert ect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 5/17/2021

## Inspection Photos



**Photo 2.** Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 5/17/2021

## Inspection Photos



**Photo 3.** There is vehicle rutting along the main road. Areas of rutting need to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 5/17/2021

## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06340 | Date: 5/17/2021