

Inspection Photos
Operator: Hilcorp
API: 067-08295
Date: 5/17/2021



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the northwestern corner facing eastward. Revegetation is progressing with a mixture of grasses such as western wheatgrass and smooth brome.



Photo 3. View of northern project area from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Oregon grape, *Poa secunda*, and serviceberry.



Photo 5. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Oregon grape, *Poa secunda*, and serviceberry.