

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/17/2021

Submitted Date:

05/18/2021

Document Number:

700702750**FIELD INSPECTION FORM**

Loc ID 335119	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10531</u> Name of Operator: <u>GRIZZLY OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277335	WELL	PR	11/24/2005	GW	045-10678	ANCHONDO 42B-20-692	PR
277336	WELL	PR	11/04/2005	GW	045-10679	ANCHONDO 42D-20-692	PR
277337	WELL	PR	12/29/2005	GW	045-10680	ANCHONDO 32D-20-692	PR
277338	WELL	PR	10/28/2005	GW	045-10681	ANCHONDO 32B-20-692	PR
290416	WELL	PR	05/03/2012	GW	045-14104	ANCHONDO 32A-20-692	PR
290417	WELL	PR	04/17/2012	GW	045-14103	ANCHONDO 32C-20-692	PR
290418	WELL	PR	10/09/2007	GW	045-14102	ANCHONDO 42A-20-692	PR
290419	WELL	PR	10/03/2007	GW	045-14101	ANCHONDO 42C-20-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 5/17/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Anchando, at Location # 335119 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection. C/A's from previous inspection document # 700701997 have NOT been completed.

During this inspection the following compliance issues were observed:

1. Location shows signs of lack of stabilization C/A is from previous inspection Document # 700701997 (C/A date 1/11/2021)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 8		corrective date
Comment:	Braden heads have a port for manual gauge monitoring		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,
Comment:	Two (2) tanks are NOT heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	Ignitor/Combustor	
Comment:	tied into tank battery	
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277335	Type:	WELL	API Number:	045-10678	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	277336	Type:	WELL	API Number:	045-10679	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	277337	Type:	WELL	API Number:	045-10680	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	277338	Type:	WELL	API Number:	045-10681	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290416	Type:	WELL	API Number:	045-14104	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290417	Type:	WELL	API Number:	045-14103	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290418	Type:	WELL	API Number:	045-14102	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	290419	Type:	WELL	API Number:	045-14101	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Culverts				
Berms						
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.  
 1. Location shows signs of lack of stabilization C/A is from previous inspection Document # 700701997 (C/A date 1/11/2021)

Corrective Action: **Install or repair required**

Date: 01/11/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402693321	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432867">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432867</a>
700702754	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432861">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432861</a>