

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM B#7**  
**Location ID: 318400**



**Photo 1 WH sign faded**



**Photo 2 Material being pushed off road no BMP.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM B#7**  
**Location ID: 318400**



**Photo 3 Berms have holes and are in disrepair.**



**Photo 4 draining separator on ground.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM B#7**  
**Location ID: 318400**



**Photo 5 road in disrepair no BMPs**

**Photo 6 Stained soil and Mechanical issues with recirc pump.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM B#7**  
**Location ID: 318400**



Colorado Oil and Gas Conservation Commission  
40.08451, -104.99643, 1512.5m  
Jun 29, 2021 11:25:29



Colorado Oil and Gas Conservation Commission  
40.08443, -104.99658, 1512.0m  
Jun 29, 2021 11:25:47

**Photo 7 produced water tank**

**Photo 8 Stained soil under crude oil load lines.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM B#7**  
**Location ID: 318400**



**Photo 9 NFPA placards faded**



**Photo 10 Stained soil and Mechanical issues Crude oil load lines.**

Inspection Photos  
Location Name: UPRR 43 PAN AM B#7  
Location ID: 318400




Photo 11 Meter calibration card out of date