

Inspection Photos

6/30/2021

Operator: WINDSOR ENERGY GROUP LLC -
10081

Location ID: 315696
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



June 30, 2021
40.10589102N 108.85723785W

Photo 1: Photo taken from the northern access road, facing west; gravel/road base remains evident; compaction alleviation, recontouring and revegetation activities not performed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 2: Photo taken from access road. Photo shows noxious weed (Halogeton) establishment.



Inspection Photos
Operator Name: WINDSOR ENERGY GROUP LLC - 10081
Location ID: 315696



Photo 3: Photo shows trash debris along access road; trash debris not removed and properly disposed per corrective actions.



Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 4: Photo taken along the access road. Photo shows erosion degradation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 5: Photo taken from the access road, facing north. Compaction alleviation, recontouring and revegetation activities not performed.



Inspection Photos
Operator Name: WINDSOR ENERGY GROUP LLC - 10081
Location ID: 315696



Photo 6: Photo taken from the access road, facing south. Photo shows trash debris along access road; trash debris not removed and properly disposed per corrective actions.



Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 7: Photo taken from the east end of the Location, facing east. Photo shows pipe equipment remaining on the Location.



Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 8: Photo taken from the access road, facing east. Photo shows trash debris along access road; trash debris not removed and properly disposed per corrective actions.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 10: Photo taken from the north end of the Location, facing South. Location has not been reclaimed in accordance with 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 11: Photo taken from the north end of the Location, facing east. Location has not been reclaimed in accordance with 1004 Rules.



Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC - 10081

Location ID: 315696



Photo 12: Photo taken from the southern access road, facing southeast. Compaction alleviation, recontouring and revegetation activities not performed.

