

**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 1 – Spill area with open excavation.**



**Photo 2 – Open excavation with groundwater.  
Impacts appear to remain in situ in southern wall.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 3 – Open excavation. Hydrocarbon sheen observed on groundwater.**



**Photo 4 – Impacts remain in-situ in southern wall.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 5 – Open excavation. Hydrocarbon sheen observed on groundwater.**



**Photo 6 – One monitoring well installed outside of open excavation.**



**Inspection Photos**  
**UPRR 43 PAN AM G Consolidation #2**  
**Remediation Project #16131/Spill ID 478086 (CL)**



**Photo 7 – Groundwater removed from open excavation being stored on site.**



**Photo 8 – Soils stockpiled on location with inadequate BMPs.**