

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2021

Submitted Date:

07/02/2021

Document Number:

701101691

FIELD INSPECTION FORM

Loc ID 334511 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---------------------------------------|---------------------------------|
| COGCC, Laramie | 970-248-0497 | cogccnotifications@laramie-energy.com | All inspections |
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 278102 | WELL | PR | 04/23/2014 | GW | 077-08900 | ESPERANZA 8-6 | PR |
| 278410 | WELL | PR | 10/23/2018 | GW | 077-08913 | ESPERANZA 8-5 | PR |
| 278411 | WELL | PR | 10/13/2015 | GW | 077-08912 | ESPERANZA 8-10 | PR |
| 278497 | WELL | PR | 04/23/2014 | GW | 077-08916 | ESPERANZA FEDERAL 8- | PR |
| 278498 | WELL | PR | 02/09/2016 | GW | 077-08915 | ESPERANZA FEDERAL 8- | PR |
| 278499 | WELL | PR | 10/09/2005 | GW | 077-08914 | ESPERANZA FEDERAL 8- | PR |

General Comment:

[COGCC Routine Inspection Report Summary](#)
During this inspection the following compliance issues were observed:
• No battery sign at tank battery.
Install sign to comply with Rule 605.e.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | No battery sign at tank battery. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 10/03/2021 |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|-------|
| Comment: | 911 | | |
| Corrective Action: | | Date: | _____ |

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

| Type | | | | corrective date |
|---------------------------------|---------------------------|-------|--|-----------------|
| Type: Bird Protectors | # 2 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |
| Type: Plunger Lift | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |
| Type: Bradenhead | # 6 | | | |
| Comment: | Bradenhead is accessible. | | | |
| Corrective Action: | | Date: | | |
| Type: Vertical Heated Separator | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

| Tanks and Berms: | | | | | |
|-------------------------|----------|---------------------|---------------------|-------------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 4 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 278102 | Type: | WELL | API Number: | 077-08900 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278410 | Type: | WELL | API Number: | 077-08913 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278411 | Type: | WELL | API Number: | 077-08912 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278497 | Type: | WELL | API Number: | 077-08916 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278498 | Type: | WELL | API Number: | 077-08915 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 278499 | Type: | WELL | API Number: | 077-08914 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | | | | | |
| Seeding | | | | | | |
| Ditches | | | | | | |
| | | Ditches | | | | |
| | | Gravel | | | | |
| | | Culverts | | | | |
| Compaction | | | | | | |
| | | Compaction | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 402737290 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470449 |
| 701101692 | Inspection 701101691 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5470444 |