

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2021

Submitted Date:

07/08/2021

Document Number:

688310819

FIELD INSPECTION FORM

Loc ID 320721 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204649	WELL	PR	05/01/2020	OW	005-06734	STATE 1-26	PR

General Comment:

[High Priority Inspection](#)

[Stained soil in engine shed.](#)

[Golden Eagle in the area](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Maintain NFPA labels (see attached photos).		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-825-4822

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in engine shed (see attached photo).		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Requires appropriate cleanup.	Date:	07/12/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Prime Mover	# 1		corrective date
Comment:	gas engine		

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Form 17 required annually.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	riser present, soil ripped in flowline area by gas sales line people, not seeded		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Comment:		
Corrective Action:		Date:

Wells Served By Facilities Above

AirsID

API Number
005-06734

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204649 Type: WELL API Number: 005-06734 Status: PR Insp. Status: PR

Producing Well

Comment: [PR 4/1/2021 production reported to COGCC database. No gas production reported recently.](#)

[Document #401670022 04 \(--VENT_FLARE\) -00 Attachment count: 3 APPROVED 11/3/2020](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention		
Gravel	Pass	Gravel	Pass			

Comment: [See attached photo of engine oil drum on the ground, needs maintenance and check that no stained soil is present.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402742741	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5474769
688310833	KPK State 1-26	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5474761