

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2021

Submitted Date:

07/09/2021

Document Number:

693700833

FIELD INSPECTION FORM

 Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	SI	04/01/2021	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	AC	01/29/2021		-	Longmont Farms Unit #5 Flowline	EI

General Comment:
[COGCC Inspection of Spill ID 479267 and followup to Field Inspection Report 693700804.](#)

Inspected Facilities

Facility ID: 245427 Type: WELL API Number: 123-13222 Status: SI Insp. Status: EI

Facility ID: 479267 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: No Operator personnel or equipment onsite at time of inspection. Inspection is open with approximate dimensions of 50'W x 60'L x 20'D. No water is present in the excavation. Ends of flowline are exposed in the north and south walls of excavation. Cattle panel fence is down on south side of excavation. Bermed area of oily waste from last inspection has been removed. Apparent clean overburden of 50 cubic yards is staged east of excavation. What appears to be a 1" diameter piezometer has been installed adjacent the east side of the excavation.

Corrective Action: Operator to submit Form 27 with Site Investigation and Remediation Workplan for remediation of Spill (this was due by April 19, 2021). Form 27 shall include any confirmation soil sample results collected to date, proposed schedule for further remediation activity, confirmation samples of clean overburden, boring log and well construction diagram with groundwater analytical results for piezometer installed. Operator also to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure and resolution of Spill via Work proceeding under a Form 27. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.

Date: 04/28/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402743510	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475620
693700838	Longmont Farms Unit 5 Farms 7-9-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5475578