

Inspection Photos
Location Name: jacobucci Jean #1
Location ID: 317872



Photo 1 loc pic



Photo 2 Stained soil in front of and around well head. Well head mechanical issues.

Inspection Photos
Location Name: jacobucci Jean #1
Location ID: 317872



Photo 3 Stained soil and mechanical issues PU motor skid



Photo 4 Stained soil and mechanical issues PU motor skid