

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2021

Submitted Date:

07/30/2021

Document Number:

699803477**FIELD INSPECTION FORM**Loc ID 311558 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210782	WELL	PR	11/04/1987	GW	045-06540	MOBIL W-29-26	PR
265375	WELL	PR	02/17/2003	GW	045-09001	PA 14-26	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 7/30/21 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC MOBIL-66S95W /26SWSW, Location #311558 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

- 1) Unmarked deadman with a corrective action date of 8/14/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 8/14/21.

- The Location is located in a high priority habitat area. All drainages contribute to the Colorado River.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		

Comment:	Unmarked deadman.		Date:	08/14/2021
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height.		Date:	08/14/2021
Type: Deadman # & Marked	# 3			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:	All meter runs have been calibrated in the last year		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: De Paolo, Corey

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Check Dams				
Ditches						
		Sediment Traps				
		Compaction				
Other	Fail					No form of tracking BMP at entrance to location
Compaction	Fail					Location lacks stabilization
		Gravel				
		Berms				
Gravel	Fail					Gravel insufficient
		Ditches				
Sediment Traps						

Comment: [Location lacks stabilization. No form of tracking BMP at entrance to location.](#)Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 08/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to equipment and Storm water for corrective actions.</a>	depaoloc	07/30/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402767043	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495103</a>
699803478	Photos for Insp. #699803477	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495086">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5495086</a>