

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2021

Submitted Date:

08/10/2021

Document Number:

699803531

FIELD INSPECTION FORM

 Loc ID 334752 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 19 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277791	WELL	PR	07/12/2012	GW	045-10774	FEDERAL 30-3BB (PD30)	PR
277794	WELL	PR	01/26/2012	GW	045-10771	FEDERAL 30-5(PD30)	PR
277795	WELL	PR	01/26/2012	GW	045-10770	FEDERAL 30-3(PD30)	PR
278495	WELL	PR	02/02/2012	GW	045-10884	FEDERAL 30-4(PD30)	PR
278496	WELL	PR	08/01/2020	GW	045-10883	FEDERAL 30-4BB (PD30)	PR
412494	WELL	PR	01/26/2012	GW	045-18462	FEDERAL 19-14BB (PD30)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 8/10/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, a follow up inspection at CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW, Location #334752 in Garfield County Colorado.

Refer to document #699802955 inspection conducted on 4/20/21. Previous corrective actions have not been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a previous corrective action date of 7/20/21.
- 2) Separator bath missing required information with a corrective action date of 10/10/21.
- 3) Flow line heating insulation open ended and not capped with a corrective action date of 8/17/21.

- The Location is located in a high priority habitat area. All drainages contribute to the Colorado River.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	07/20/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator bath missing required information.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled.	Date:	10/10/2021
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellheads		
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	Flow line heating insulation open ended and not capped.	Date:	
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date:	08/17/2021
Type: Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>277791</u>	Type:	<u>WELL</u>	API Number:	<u>045-10774</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>277794</u>	Type:	<u>WELL</u>	API Number:	<u>045-10771</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>277795</u>	Type:	<u>WELL</u>	API Number:	<u>045-10770</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>278495</u>	Type:	<u>WELL</u>	API Number:	<u>045-10884</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>278496</u>	Type:	<u>WELL</u>	API Number:	<u>045-10883</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>412494</u>	Type:	<u>WELL</u>	API Number:	<u>045-18462</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Berms				
		Gravel				
		Ditches				
Sediment Traps						
Berms						
		Sediment Traps				
Compaction						
		Compaction				
Gravel						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers and Equipment for corrective actions.	depaoloc	08/10/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402776673	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5503371
699803532	Photos for Insp. #699803531	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5503359