

Inspection Photos

API: 071-08105

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/16/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing northeast toward the access road. The culvert shown at red arrow is filled in with sediment. Stormwater flowed across the road in this area. The culvert will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 8/16/2021

Inspection Photos



Photo 2. Erosion at the culvert outlet has exposed the pipe line shown at red arrow. This area will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 8/16/2021

Inspection Photos



Photo 3. Stormwater erosion is occurring down the road. The road will need to be graded and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 8/16/2021

Inspection Photos



Photo 4. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08105 | Date: 8/16/2021