

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2021

Submitted Date:

08/23/2021

Document Number:

679604114**FIELD INSPECTION FORM**Loc ID 327053 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 88265Name of Operator: TIGGES OIL LLCAddress: 12406 WCR 64 1/2City: GREELEY State: CO Zip: 80631**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
		jesse.tigges@gmail.com	
Tigges, Kenneth	970-396-8381	levi.tigges@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
56731	WELL	SI	08/01/2020	OW	123-14072	TIGGES 3-31B	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Pumpjack sign displays wrong well name. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2021
Type	TANK LABELS/PLACARDS		
Comment:	one fiberglass tank does not contain labeling. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/09/2021
Type	BATTERY		
Comment:	Sign is not legible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/09/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment near pumpjack, inside tank battery, and unused riser near separator. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	06/09/2021
Type	WEEDS		
Comment:	Weeds inside tank battery berm and near separator and ECD. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	06/09/2021
Type	OTHER		
Comment:	Stained soil at pumpjack. See attached photos.		
Corrective Action:	Comply with Rule 608.e.	Date:	06/09/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	According to COGCC maps, location is within floodplains (FEMA). Berm surrounding tank battery is inadequate. See attached photos.				
Corrective Action:	Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3). Refer to the 603.h guidance document for further details.				Date: 06/09/2021

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:		Shares containment with other tanks.						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
OTHER	1	OTHER	FIBERGLASS AST		,			
Comment:								
Corrective Action:							Date:	
Paint								
Condition	Adequate							
Other (Content)	UNKNOWN							
Other (Capacity)	UNKNOWN							
Other (Type)								
Berms								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Comment:		Shares containment with crude, produced water tanks.						
Corrective Action:							Date:	
Venting:								
Yes/No	NO							
Comment:								
Corrective Action:							Date:	
Flaring:								
Type								
Comment:								
Corrective Action:							Date:	

Inspected Facilities									
Facility ID:	56731	Type:	WELL	API Number:	123-14072	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT ONSITE									
Comment: <input type="text"/>									
Corrective Action: <input type="text"/> Date: <input type="text"/>									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603733. All previous corrective actions that were originally assigned to this location have not been resolved and have been re-assigned to this location. No new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Monday, August 23, 2021 at approximately 13:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at TIGGES 3-31B (Tigges Oil, LLC), at location #: 327053 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. Pumpjack sign displays wrong well name. Install sign to comply with Rule 605.d. (Corrective Action Date: June 9, 2021) See attached photo #1. 2. Tank Battery signage is no longer legible. Install sign to comply with Rule 605.h. (Corrective Action Date: June 9, 2021) See attached photo #2. 3. One fiberglass tank does not contain any labeling (contents, capacity, NFPA placard) Install signage to comply with Rule 605.h. (Corrective Action Date: June 9, 2021) See attached photo #11. 4. Weeds inside tank battery berm and near the ECD and separator. Remove weeds to comply with Rule 606. (Corrective Action Date: June 9, 2021) See attached photos #6-11. 5. Unused equipment/storage of equipment on various spots of location and one unused riser near separator. Remove or reconnect equipment on location. Operator has 24 HRS to LO/TO riser; remove if not in use per Rule 606. (Corrective Action Date: June 9, 2021) See attached photos #4-6, 8. 6. Inadequate earth berm surrounds tank battery. Location is within a floodplain, containment berms around the tanks must be made of steel or another engineer equivalent per Rule 421.b.(3). Refer to the 603.h guidance document for further details. (Corrective Action Date: June 9, 2021) See attached photos # 9-11. 7. It appears to be stained soil at pumpjack (north and south of pumpjack) Remove to comply with Rule 608.e. (Corrective Action Date: June 9, 2021) See attached photos #3, 4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	08/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402791129	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5514314
679604115	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5514309