

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2021

Submitted Date:

08/27/2021

Document Number:

693700858**FIELD INSPECTION FORM**Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	SI	04/01/2021	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	CL	07/19/2021		-	Longmont Farms Unit #5 Flowline	EI

General Comment:

Inspected Facilities								
Facility ID:	245427	Type:	WELL	API Number: 123-13222	Status:	SI	Insp. Status:	EI
Facility ID:	479267	Type:	SPILL OR	API Number: -	Status:	CL	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: No Operator personnel or equipment onsite at time of inspection. A fiberglass flowline is exposed in northwest corner of excavation. Fence is now composed of a combination of cattle panel and snow fence. Fencing currently appears to be intact but may be quickly undermined with the collapse of an excavation wall. Fence is along edge of excavation walls and south wall of excavation is experiencing erosion from stormwater. Additional storm events pose a hazard of collapsing the excavation wall and undermining the fence. Stockpile east of excavation has earthen berm.

Operator has submitted a Form 27, Document #402777901, REM 18932 in review by COGCC. Operator has not supplied the information required on a Form 19 as specified in the previous inspection: "Operator also to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.

Corrective Action: Operator to identify fiberglass line and contact COGCC Engineering Integrity Group for Abandonment or repair pursuant to Rules 1102 and 1105.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ **Wildlife Protection Devices (fired vessels):** _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402795345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517961
693700859	Longmont Farms Unit 5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517946