

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2021

Submitted Date:

08/13/2021

Document Number:

694500365

FIELD INSPECTION FORMLoc ID 316767 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10282

Name of Operator: EPHPHATHA LLC

Address: 1314 B CENTER DR #449

City: MEDFORD State: OR Zip: 97501

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waldron, Emily		emily.waldron@state.co.us	
Garrison, Penny		penny.garrison@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Sullins, Cory	(310) 901-1996	csullins03@yahoo.com	
Andrews, Dave		david.andrews@state.co.us	
Sills, Shane	310) 901-1996	shanesills@gmail.com	
Burger, Craig		craig.burger@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232759	WELL	DA	12/21/1991	DA	107-06174	DRY CREEK UT HD 31 1	EI
232760	WELL	SI	08/01/2019	OW	107-06175	DRY CREEK UT HD 31 1A (PILOT HOLE)	EI

General Comment:

On 8/12/2021 COGCC staff, Kris Neidel inspected 081-06175 location with COGCC Inspector Emily Waldron. Weather was dry and 85 degrees at the time of the inspection. The following was observed on location; Wellhead with pump rod exposed, surface flowline, 1 above ground tank, the surface flowline is plumbed from wellhead to tank, no pump is present on location, all production equipment is fenced with cyclone panels, weeds cover location and access road. Well 107-06175, also on location, has been converted to a water well and contained in a shed that is also fenced. The last MIT date was 7/10/2017 (per doc 402637859, next MIT due is 7/10/2022).
Corrective Actions: install proper labels on Tank, Address Weeds. Photos Attached.

Location

Lease Road:			
Type	Access		
comment:	Access overgrown with weeds and other vegetation.		
Corrective Action	Comply with Rule 606	Date:	08/26/2021

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	No label on tank. Battery sign on tank		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/12/2021

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Annual and noxious weeds on location, see photos and inspection doc 402778815.		
Corrective Action:	Comply with Rule 606.	Date:	08/19/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	#		
Comment:	Bradenhead inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 08/23/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		STEEL AST		
Comment:	No label on tank. Note: "contents" and "Capacity" left blank as they are on tank. Tank appears to be 400bbl.				
Corrective Action:	Install labels to comply with Rule 605.h.				Date: 10/12/2021

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: NEIDEL, KRIS

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: stormwater was present in berm.					
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected FacilitiesFacility ID: 232759 Type: WELL API Number: 107-06174 Status: DA Insp. Status: EI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: 09/13/2021Facility ID: 232760 Type: WELL API Number: 107-06175 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402795149	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517755
694500366	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5517752