

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2021

Submitted Date:

09/24/2021

Document Number:

688000551

**FIELD INSPECTION FORM**

Loc ID 320112 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10711  
 Name of Operator: PAINTED PEGASUS PETROLEUM LLC  
 Address: 16820 BARKER SPRINGS RD #521  
 City: HOUSTON State: TX Zip: 77084

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Robert		robert.chesson@state.co.us	
		khubbard@P3Petro.com	
		jmustacchia@p3petro.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202658	WELL	SI	07/01/2021	GW	001-08063	HORTH 41-15 1	EI

**General Comment:**

Environmental inspection to document the cleanup status of previously reported oily soil at the wellhead and near the partially buried vault.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202658 Type: WELL API Number: 001-08063 Status: SI Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: See FI 700900640 (8/13/21) for photos. Oily soil remains at the wellhead and within the tank battery as of this inspection, see attached photos.

Corrective Action: "Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPSstaff. Immediately to stop and clean up 24 hours to remove free fluids. Corrective Action Date 9/17/2021. See attached photo # 4, 5 & 6" Date: 09/17/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402823588	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540875">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540875</a>
688000552	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540165">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5540165</a>