

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2021

Submitted Date:

10/06/2021

Document Number:

695104890

FIELD INSPECTION FORM

Loc ID 308316 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
GEE, GREG	903-987-0353	ggee@ogrisop.com	All Inspections
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266156	WELL	PR	11/19/2018	GW	071-07815	HILL RANCH 34-16	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	PHOTO 2: WELL SIGN/ SIGN IS WEATHERD AND OUT OF COMPLIANCE.		
Corrective Action:	Install sign to comply with Rule 605.a. (NOTE: THE NEW RULES REQUIRE THE API # TO BE POSTED ON NEW SIGNS).	Date:	01/06/2022

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: PUMPJACK MOTOR IS LEAKING AND RUNNING OFF CONCRETE BASE IMPACTING SOIL AROUND JUMPJACK BASE.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D.	Date:	10/13/2021

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Count	Comment	Corrective Action	Date
Deadman # & Marked	# 4	ALL HAVE MARKERS		
Pump Jack	# 1			
Bradenhead	# 1	IS PLUMBED TO SURFACE		
Gas Meter Run	# 1	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Ancillary equipment	# 1	TELEMETRY EQUIPMENT		
Vertical Separator	# 1			

Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 266156 Type: WELL API Number: 071-07815 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:
 Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 292656 Lat: 37.033600 Long: -104.867300
 Reference Point: SE Other: _____ Length: 70 Width: 70

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment:
 Corrective Date: _____

Fencing:
 Fencing Type: None Fencing Condition: _____
 Comment:
 Corrective Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: NONE
 Corrective Date: _____
 Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES
 Comment:
 Corrective Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402833790	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5548974
695104891	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5548962