

Inspection Photos
Operator: Simcoe
Loc ID: 471426
Date: 10/13/2021



Photo 1. View of gas line right of way, facing eastward. Dense Russian knapweeds observed. Within and outside of the project area.



Photo 2. View of dense Russian knapweeds along the fenceline within the right of way, facing eastward. Weeds are not being controlled.



Photo 3. View of area along the right of way where little desirable vegetation is present. Inset shows rodent holes in bare soils.



Photo 4. Another view of bare soils along the right of way, needing revegetation.



Photo 5. View of sign debris within the project area, needs to be removed.