

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2021

Submitted Date:

10/18/2021

Document Number:

696105165

FIELD INSPECTION FORMLoc ID 310872 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297520	WELL	PA	07/01/2020	GW	123-27164	KEHN USX AA 01-02	PA

General Comment:

This is a PLUGGED & ABANDONED WELL inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID
(302162).
(Well(s): 1: Shut-In | SI).

Centralized Battery formerly served 1 Location ID
(310872).
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696104692 and/or Location ID #302162
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696104694 dated 07/08/2021.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

0

Comment:

Prior insp:
 Unnecessary equipment (Tubing) at Plugged & Abandoned wellsite.
 Refer to Rule 606 for guidance.
 *Remove unnecessary equipment from Plugged & Abandoned wellsite.
 Comply with Rule 606.
 Corrective Action date: 10/11/2021.

This insp:

**Unnecessary equipment (Tubing) at Plugged & Abandoned | PA wellsite
 has been removed.
 See photos #2 & 3.

Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 297520 Type: WELL API Number: 123-27164 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 10/18/2021 at approximately 15:23 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: KEHN USX AA-66N63W /1NWNE Location ID: 310872 Well Name(s): Kehn USX AA 01-02. API: 05-123-27164. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (302162). (Well(s): 1: Shut-In SI).</p> <p>Centralized Battery formerly served 1 Location ID (310872). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696104692 and/or Location ID #302162 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696104694 dated 07/08/2021.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #402446314 indicates plugging, cut/cap date: 04/16/2020. Approved.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Unnecessary equipment (Tubing) at Plugged & Abandoned wellsite. Refer to Rule 606 for guidance. *Remove unnecessary equipment from Plugged & Abandoned wellsite. Comply with Rule 606. Corrective Action date: 10/11/2021. **Unnecessary equipment (Tubing) at Plugged & Abandoned PA wellsite has been removed. See photos #2 & 3.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/18/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105166	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558111