

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/12/2021

Submitted Date:

10/12/2021

Document Number:

700703357

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 413466 \_\_\_\_\_ Ramsey, Scott \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

3 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412626	WELL	PR	02/16/2012	GW	103-11529	Piceance Creek Unit 296-6B5	PR
412628	WELL	PR	02/18/2012	GW	103-11530	Piceance Creek Unit 296-6B4	PR
412650	WELL	PR	09/01/2020	GW	103-11531	Piceance Creek Unit 296-6B7	PR
412651	WELL	PR	01/01/2021	GW	103-11534	Piceance Creek Unit 296-6B8	PR
412652	WELL	PR	02/26/2012	GW	103-11533	Piceance Creek Unit 296-6B10	PR
412653	WELL	PR	02/27/2012	GW	103-11532	Piceance Creek Unit 296-6B9	PR
413071	WELL	PR	02/24/2012	GW	103-11546	Piceance Creek Unit 296-6B1	PR
413072	WELL	SI	02/01/2020	GW	103-11545	PICEANCE CREEK UNIT 296-6B2	TA
413073	WELL	PR	12/01/2017	GW	103-11547	Piceance Creek Unit 296-6B6	PR
413074	WELL	PR	02/21/2012	GW	103-11548	Piceance Creek Unit 296-6B3	PR

**General Comment:**

COGCC Inspection Report Summary

On Monday 10/12/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus Piceance Unit 296-6B, at Location # 413466 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Random debris
2. Well head cellar is open for wildlife to enter
3. Cut slope shows signs of lack of stabilization/erosion

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Entrance to location		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Well head cellar is open for wildlife to enter		
Corrective Action:	Eliminate possibility of wildlife to enter		Date: <u>10/22/2021</u>
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris		Date: <u>10/22/2021</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Horizontal Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 10		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well head is drilled and cemented not completed yet		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	412626	Type:	WELL	API Number:	103-11529	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	412628	Type:	WELL	API Number:	103-11530	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	412650	Type:	WELL	API Number:	103-11531	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	412651	Type:	WELL	API Number:	103-11534	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	412652	Type:	WELL	API Number:	103-11533	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	412653	Type:	WELL	API Number:	103-11532	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	413071	Type:	WELL	API Number:	103-11546	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	413072	Type:	WELL	API Number:	103-11545	Status:	SI	Insp. Status:	TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well head is drilled and cemented not completed yet. Last MIT was done 6/28/2019

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 413073 Type: WELL API Number: 103-11547 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 413074 Type: WELL API Number: 103-11548 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. Cut slope shows signs of lack of stabilization/erosion

Corrective Action: Install or repair required BMPs

Date: 12/17/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402839565	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553308</a>
700703361	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553303">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5553303</a>