

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2021

Submitted Date:

10/13/2021

Document Number:

699803712

FIELD INSPECTION FORMLoc ID 334775 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288424	WELL	PR	12/14/2006	GW	045-13282	KNIGHT PA 21-3	PR
288425	WELL	PR	12/14/2006	GW	045-13281	KNIGHT PA 321-3	PR
288426	WELL	PR	12/14/2006	GW	045-13280	KNIGHT PA 422-3	PR
288427	WELL	PR	12/14/2006	GW	045-13279	KNIGHT PA 322-3	PR
288428	WELL	PR	12/14/2006	GW	045-13278	KNIGHT PA 22-3	PR
288429	WELL	PR	12/14/2006	GW	045-13277	KNIGHT PA 421-3	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/12/21 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /3NENW, Location #334775 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Horizontal separator includes glycol storage tank. Glycol storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Glycol storage tank missing required information.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Horizontal separator includes glycol storage tank. Glycol storage tank is approximately 2'x3'x14' with an approximate capacity of 15 barrels. Glycol storage tank missing required information.		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled with Name of operator, Operator's emergency contact telephone number, Tank capacity, Tank contents, and NFPA label or equivalent globally harmonized label.	Date:	12/12/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		

Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	288424	Type:	WELL	API Number:	045-13282	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288425	Type:	WELL	API Number:	045-13281	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288426	Type:	WELL	API Number:	045-13280	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288427	Type:	WELL	API Number:	045-13279	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288428	Type:	WELL	API Number:	045-13278	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	288429	Type:	WELL	API Number:	045-13277	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Ditches						
		Culverts				
		Ditches				
Compaction						
Berms						
		Sediment Traps				
				Material Handling And Spill Prevention		Chemical tank
Gravel						
		Gravel				
Sediment Traps						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Sign/Markers for corrective actions.	depaoloc	10/13/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402841976	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555164
699803713	Photos for Insp. #699803712	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5555161