

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/20/2021

Submitted Date:

10/25/2021

Document Number:

701003752

**FIELD INSPECTION FORM**
 Loc ID 338174 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293462	WELL	PR	08/01/2020	GW	125-11053	SCHAFER 22-25	PR

**General Comment:**

Routine Inspection

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel road through pasture			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Lease signs mounted on meter sheds			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Lease sign by unit. Sticker is peeling off and needs replaced			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Metal panels around VGS and meter sheds			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Metal panels around unit and wellhead			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Prime Mover	# 1			corrective date
Comment:	Electric motor			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Sentry unit			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	Shared meter run for (Schafer 11-25, 13-25, 22-25) 600' WSW			
Corrective Action:				Date:

Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter sheds		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	293462	Type:	WELL	API Number:	125-11053	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Schafer 11-25, 13-25, 22-25) 600' WSW @ 39.76766/-102.25179								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Compaction	Fail			

Comment: [Access has erosion and needs maintenance](#)Corrective Action: [Repair erosion on access](#)

Date: 11/20/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701003766	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563145">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563145</a>