

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2021

Submitted Date:

10/15/2021

Document Number:

701102063

**FIELD INSPECTION FORM**Loc ID 314716 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL &amp; GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Heil, John		john.heil@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229394	WELL	SI	12/01/2019	OW	103-07049	GEBAUER 14	SI

**General Comment:**

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No Api# on well sign.
- Casing gas coming out of 2 holes in top plate of well.
- Dead weed debris covering location, pit, and tank berm.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Unmaintained		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No api # on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/19/2022
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Dead weed debris covering location, pit, and tank berm.		
Corrective Action:	Comply with 606	Date:	11/19/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Open to atmosphere.		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Markers not brightly colored.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Dead weed debris in tank berm. See housekeeping report.			
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Casing gas coming out of 2 holes in top plate of well.	
Corrective Action:	Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.	Date: 04/23/2021

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 229394 Type: WELL API Number: 103-07049 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last reported operation in May 2020, and last reported production November 2019. MIT will be required in November 2021. (next month)Corrective Action: 

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Date: **Fencing:**Fencing Type: Livestock

Fencing Condition:

Comment: Corrective Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Date: 

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402846367	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558638">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5558638</a>