

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2021

Submitted Date:

10/25/2021

Document Number:

701003761

FIELD INSPECTION FORM

Loc ID 321788 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208023	WELL	TA	04/24/2019	OW	017-06958	KERN 34-3 2	TA

General Comment:

[Routine Inspection](#)

Location

Lease Road:

Type	Other				
comment:	Access wellhead through farm ground				
Corrective Action				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	Lease sign at wellhead				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	

Good Housekeeping:

Type	DEBRIS				
Comment:	Metal fence, pipe and fittings laying around location				
Corrective Action:	Comply with Rule 606			Date:	11/05/2021

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Gas Meter Run	# 0			
Comment:	Removed from location			
Corrective Action:				Date:
Horizontal Heater Treater	# 0			
Comment:	Removed from location			
Corrective Action:				Date:
Ancillary equipment	# 0			
Comment:	Removed from location			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	300 BBLs	STEEL AST		38.857140,-102.098620
Comment:	Tanks removed from location				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	300 BBLs	STEEL AST		38.857140,-102.098410
Comment: Tanks removed from location					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 208023 Type: WELL API Number: 017-06958 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402851939	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563170
701003762	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5563150